



























	200 mm		3/8"
	160 mm		3/8" 75 mm
			3/8" 150 mm
	180 mm		1/4" 4-4,5-5-5,5-6-7-8-9 mm
			3/8" 10-11-12-13-14-15-17-18-19mm
	240 mm		3/8" x 21 mm
			1/4" x 3/8"
	200 mm		3x75, 4x80, 5x100, 6.5x125 mm
	200 mm		PH1x80, PH2x100 mm
	18 mm		
			
	18 mm		200-250 V, 140 mm, CE
			PH0 1.5 mm
	1,5 - 10 mm		150 mm
	6x7, 8x9, 10x11, 12x13, 14x15, 16x17, 18x19, 20x22 mm		300 mm
	180 mm		300 g
	3 m		



⊕ PH0, PH1x2, PH2x2, PH3






























⊗ Torx: 10, T15, T20, T25, T27, T30


○ H2,5 - H3 - H4 - H5 - H5,5 - H6

 60 mm

⊕ PZ0, PZ1x2, PZ2x2, PZ3

● Slotted: 3, 4, 5, 6, 6, 7 mm

	200 mm		3/8"
	160 mm		3/8" 75 mm
			3/8" 150 mm
	180 mm		1/4" 4-4,5-5-5,5-6-7-8-9 mm
			3/8" 10-11-12-13-14-15-17-18-19mm
	240 mm		3/8" x 21 mm
			1/4" x 3/8"
	200 mm		3x75, 4x80, 5x100, 6.5x125 mm
	200 mm		PH1x80, PH2x100 mm
	18 mm		
			
	18 mm		200-250 V, 140 mm, CE
			PH0 1.5 mm
	1,5 - 10 mm		150 mm
	6x7, 8x9, 10x11, 12x13, 14x15, 16x17, 18x19, 20x22 mm		300 mm
	180 mm		300 g
	3 m		



⊕ PH0, PH1x2, PH2x2, PH3






























⊗ Torx: 10, T15, T20, T25, T27, T30


○ H2,5 - H3 - H4 - H5 - H5,5 - H6

 60 mm

⊕ PZ0, PZ1x2, PZ2x2, PZ3

● Slotted: 3, 4, 5, 6, 6, 7 mm

	200 mm		3/8"
	160 mm		3/8" 75 mm
			3/8" 150 mm
	180 mm		1/4" 4-4,5-5-5,5-6-7-8-9 mm
			3/8" 10-11-12-13-14-15-17-18-19mm
	240 mm		3/8" x 21 mm
			1/4" x 3/8"
	200 mm		3x75, 4x80, 5x100, 6.5x125 mm
	200 mm		PH1x80, PH2x100 mm
	18 mm		
			
	18 mm		200-250 V, 140 mm, CE
			PH0 1.5 mm
	1,5 - 10 mm		150 mm
	6x7, 8x9, 10x11, 12x13, 14x15, 16x17, 18x19, 20x22 mm		300 mm
	180 mm		300 g
	3 m		



⊕ PH0, PH1x2, PH2x2, PH3

⊗ Torx: 10, T15, T20, T25, T27, T30

○ H2,5 - H3 - H4 - H5 - H5,5 - H6

 60 mm

⊕ PZ0, PZ1x2, PZ2x2, PZ3

● Slotted: 3, 4, 5, 6, 6, 7 mm